Order No.: DD+DIS146.02E

1 piece U937N MA1

ADC Compact Plus
Type 5146/100

Centricity CR MP3510
Type 5146/200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				X

Please file this document in chapter 10 of your technical documentation

IP jams in postscan area

1 Problem

The IP is not released after scanning
Error – Code: 24ABE; “IP plate jam in scanner”

2 Reason

Due to mechanical tolerances of IP material (stiffness of Ips) the IP cannot be released from the postscan rolls. Therefore the postscan detection light barrier GS614 is not able to detect the IP.

3 Solution

Contact HE/Im GSO.

In case of frequent IP jams check out the format (mostly large formats). A decision to exchange Ips can only be made case by case.

printed in Germany 06 / 2002

AGFA